

Inspection Photos
Location Name: Pronghorn T-P-HNB
Location ID: 431481



Photo 1 – Tank Battery



Photo 2 – Tank Battery Signs



Inspection Photos
Location Name: Pronghorn T-P-HNB
Location ID: 431481



Photo 3 – Separators and ECDs




Photo 4 – Wellhead



Inspection Photos
Location Name: Pronghorn T-P-HNB
Location ID: 431481



Photo 5 – Unmarked Riser at Pumping Unit



Photo 6 – Unmarked Riser at Pumping Unit

