

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 1 – Pumping Unit



Photo 2 – Wellhead

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 3 – Unmarked Riser at Wellhead



Photo 4 – Wellhead Sign

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 5 – Separator



Photo 6 – Unmarked Riser at Separators

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 7 – Unmarked Risers at Separators



Photo 8 – Unmarked Risers at Separators



Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 9 – 2-Phase Separator



Photo 10 – Unmarked Riser

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089




Photo 11 – Unmarked 1" Riser at Pig near Lease Road




Photo 12 – Unmarked 1" Riser at Pig near Lease Road

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 13 – Unmarked Riser



Photo 14 – Unmarked Risers



Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 15 – ECD



Photo 16 – Tank Battery

Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 17 – Tank Battery Signs



Photo 18 – Unmarked Riser on North Side of Tanks



Inspection Photos
Location Name: Pronghorn 11-14-5HZ
Location ID: 427089



Photo 19 – Capacity Label on North Produced Water Tank