

Inspection Photos  
Location Name: Martin T Hart F unit 1  
Location ID: 318222



Photo 1 WH sign

Photo 2 WH

Inspection Photos  
Location Name: Martin T Hart F unit 1  
Location ID: 318222



Photo 3 Pump Jack and ancillary equipment

Photo 4 TB sign

Inspection Photos  
Location Name: Martin T Hart F unit 1  
Location ID: 318222



Photo 5 TB

Photo 4 Gas Meter Run and Vertical Separator House.

Inspection Photos  
Location Name: Martin T Hart F unit 1  
Location ID: 318222




Photo 7 card in meter box indicates calibration is not current

Photo 8 stained soil has been cleaned up and removed.

## Inspection Photos

Location Name: Martin T Hart F unit 1

Location ID: 318222



Photo 9 Horiz. Heated Sep.



Photo 10 stained soil has been cleaned up and removed.