

Inspection Photos
Location Name: Martin T. Hart D 1
Location ID: 317907



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Martin T. Hart D 1
Location ID: 317907



Photo 3 Pump jack



Photo 4 ancillary equip.

Inspection Photos
Location Name: Martin T. Hart D 1
Location ID: 317907



Photo 5 TB sign

Photo 6 TB

Inspection Photos
Location Name: Martin T. Hart D 1
Location ID: 317907



Photo 7 Gas Meter Run




Photo 8 card in meter box indicates that calibration is not current



Inspection Photos
Location Name: Martin T. Hart D 1
Location ID: 317907



Photo 9 Horiz. Heated Separator