

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /33SWNE

Location ID: 323990



Photo #5652 from entrance to location.



Photo #5653 missing bird protectors.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /33SWNE

Location ID: 323990



Photo #4244 from inspection #699803323 conducted on 6/30/21.




Photo #5654 Storage tank not labeled.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /33SWNE

Location ID: 323990



Photo #5655 Sight glass indicates the storage tank is full of an unknown fluid.



Photo #5656 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-66S96W /33SWNE

Location ID: 323990



Photo #5657 Location lacks stabilization.



Photo #5658 Insufficient tracking BMP at entrance to location.