

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC S.PARACHUTE TBI-67S96W /36NESE**

**Location ID: 334080**



**Photo #5675 from entrance to location.**



**Photo #5676 from entrance to location.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC S.PARACHUTE TBI-67S96W /36NESE

Location ID: 334080



Photo #5677 Storage tank not labeled.




Photo #5678 Sight glass indicates the storage tank is full of an unknown fluid.



## Inspection Photos

Location Name: CAERUS PICEANCE LLC S.PARACHUTE TBI-67S96W /36NESE

Location ID: 334080



**Photo #5679 No battery sign located at the tank battery.**