

Inspection Photos
Location Name: Duncan B 12
Location ID: 313142



Photo 1. Overview of location taken facing southeast.



Photo 2. Tank labels faded/missing.

