

# Inspection Photos

API: 061-06084

Operator: CHEMCO INC

Inspection Date: 1/12/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06084 - Date: 1/12/2022

## Inspection Photos



**Photo 1.** Drone aerial photo facing down toward the plugged and abandoned well site. The area around the abandoned site is bare of vegetation which indicates impacted soils from oil and gas operations.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06084 - Date: 1/12/2022



## Inspection Photos



**Photo 2.** Facing south toward the abandoned well site. The location is bare of vegetation on approximately 150'x120' area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06084 - Date: 1/12/2022

## Inspection Photos



**Photo 3.** Center of the location facing south. The area around the abandoned site is bare of vegetation which indicates impacted soils from oil and gas operations.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06084 - Date: 1/12/2022