

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/12/2022

Submitted Date:

01/14/2022

Document Number:

699602640

FIELD INSPECTION FORM

Loc ID 429642 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

14 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429644	WELL	SI	11/01/2018	OW	123-35855	BETHYL GW30-16	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive / Shut-down.

Centralized Battery serves 1 Tank Battery Facility ID (481387).
Centralized Battery serves 1 Location ID (429642).
(Well(s): 1: Shut-In | SI).

Refer to Field Inspection Report doc. #699602638 and/or Facility ID #481387 for Battery / Facility, Equipment info.

Location

Lease Road:			
	Type	Access	
	comment:	Adequate	
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
	Type	WELLHEAD	
	Comment:		
Corrective Action:			Date:

Emergency Contact Number:			
	Comment:	<input type="text"/>	
	Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	WELLHEAD	
	Comment:	Iron Panel.	
Corrective Action:			Date:
	Type	LOCATION	
	Comment:	Barbed wire.	
Corrective Action:			Date:

Equipment:			corrective date
Type: Ancillary equipment	# 2		
Comment:		1: Electric power bank. 1: ESP controller.	
Corrective Action:			Date:
Type: Emission Control Device	# 0		
Comment:		Assigned to Fac. ID 481387.	
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 0		
Comment:		Assigned to Fac. ID 481387.	
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Type: Bradenhead	# 1	
Comment:	Appears plumbed to surface.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.628580,-104.468690
Comment:	Centralized Battery serves 1 Tank Battery Facility ID (481387). Centralized Battery serves 1 Location ID (429642). Refer to Field Inspection Report doc. #699602638 and/or Facility ID #481387 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:	Assigned to Fac. ID 481387.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:	Assigned to Fac. ID 481387.				
Corrective Action:					Date:

Paint				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 429644 Type: WELL API Number: 123-35855 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Shut-In | SI.
Observed production valves shut.
Locked-Out, Tagged-Out | LOTO.
COGCC records last production: 10/2018.
SI/TA well per variance doc. #401474555. (NOBLE).

Corrective Action:

Date: _____

BradenHead

Date of Last Brhd Test: 09/01/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 01/12/2022 at approximately 15:49 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: BETHYL /GW30-16 Location ID: 429642 Well Name(s): Bethyl GW30-16. API: 05-123-35855. Location County: Weld County, Colorado Weather: Mostly Sunny, partial snow coverage from prior storm.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive / Shut-down.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481387). Centralized Battery serves 1 Location ID (429642). (Well(s): 1: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #699602638 and/or Facility ID #481387 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/14/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602641	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5633919