

# Inspection Photos

API: 061-06353

Operator: STRACHAN EXPLORATION

Inspection Date: 1/11/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06353 | Date: 1/11/2022

## Inspection Photos



**Photo 1.** Drone aerial photo facing north toward the abandoned location. The location has not been reclaimed per Rule 1004.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06353 | Date: 1/11/2022



## Inspection Photos



**Photo 2.** Facing southwest at the location. The location remains mostly bare of vegetation growth and has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06353 | Date: 1/11/2022



## Inspection Photos



**Photo 3.** Facing southwest at the location. The location remains mostly bare of vegetation growth and has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06353 | Date: 1/11/2022



## Inspection Photos



**Photo 4.** Facing north at the location. The location has not been reclaimed and there is debris that remains shown at red arrows.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06353 | Date: 1/11/2022



## Inspection Photos



**Photo 5.** Facing north toward the surrounding undisturbed pasture which consists of Blue grama, Sand drop seed, among other native species.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06353 | Date: 1/11/2022