

# Inspection Photos

ID: 150131

Operator: STRACHAN EXPLORATION INC

Inspection Date: 1/11/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Aerial image showing the SALT LAKE UNIT abandoned location and associated facility.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 1/11/2022

## Inspection Photos



**Photo 2.** Facing east toward the SALT LAKE UNIT abandoned location.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 1/11/2022

## Inspection Photos



**Photo 3.** The location has not been reclaimed. Soils have not been leveled and decompacted and gravel remains.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 1/11/2022

## Inspection Photos



**Photo 4.** Facing south at the location . The soils are bare of vegetation and the location has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 1/11/2022

## Inspection Photos



**Photo 5.** The shovel could not penetrate the compacted soils. Also observed was blackened soil with hydro carbon odor.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 1/11/2022

## Inspection Photos



**Photo 6.** The power utility at the location is in disrepair with exposed wires which is a safety concern.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 1/11/2022

## Inspection Photos



**Photo 7.** Facing north at the location. The electric powerline utilities need to be removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 1/11/2022

## Inspection Photos



**Photo 8.** Facing east toward the surrounding undisturbed pasture which consists of native Blue grama grassland.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 1/11/2022

## Inspection Photos



**Photo 9.** Facing east at the beginning of the access road from CR 27 to the Salt Lake Unit associated battery facility. The gates have fallen over and the access road was not reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 1/11/2022

## Inspection Photos



**Photo 10.** Facing north east along the access road which has not been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 1/11/2022

## Inspection Photos



**Photo 11.** Facing northeast toward the abandoned battery facility. The location is bare of vegetation and has not been reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 1/11/2022

## Inspection Photos



**Photo 12.** Drone aerial photo facing north toward the Salt Lake Unit abandoned facility showing the location and access road not reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 150131 | Date: 1/11/2022