

# Inspection Photos

API: 061-06793

Operator: STRACHAN EXPLORATION

Inspection Date: 1/11/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 061-06793 | Date: 1/11/2022

## Inspection Photos



**Photo 1.** Facing southeast toward the wellsite.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06793 | Date: 1/11/2022

## Inspection Photos



**Photo 2.** There is weed debris along the fence that needs to be removed. Fence needs maintenance to prevent livestock entry.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 061-06793 | Date: 1/11/2022