

Inspection Photos

Operator: Morningstar
API: 067-08670 Date:
1/11/2022



Photo 1. View of project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is largely grazed at this time, vegetation needs to be assessed during the active growing season.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of the reference area comprised of open grass field with grasses such as thickspike wheatgrass, western wheatgrass, and forbs such as curly doc, in a dormant vegetative condition at this time.