

Inspection Photos
Operator: Simcoe
API: 007-06203
Date: 1/11/2022



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with western wheatgrass, crested wheatgrass.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of the reference area comprised of open grass field, sagebrush shrubland, and pinyon/juniper mosaic with grasses such as thickspike wheatgrass, western wheatgrass, and mountain mahogany, pricklypear, and yucca.