

Inspection Photos  
Operator: Simcoe  
API: 067-08868  
Date: 1/11/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing here with rubber rabbitbrush, crested wheatgrass, and blue grama.



Photo 4. View of reference area, comprised of pinyon and juniper woodland with prickly pear, squirreltail, blue grama, and sagebrush in the understory.




Photo 4. View bare soils on the well pad cut-slope. Observable vegetation is largely Russian thistle weeds.