

Inspection Photos

API: 061-06023

Operator: WESTERN OPERATING COMPANY

Inspection Date: 1/12/2022



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 1/12/2022

Inspection Photos



Photo 1. Facing west toward the tank battery. The well site is located at red arrow. The tank battery is not fenced to prevent livestock entry. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 1/12/2022

Inspection Photos



Photo 2. There is oil stained soil around the tanks which need to be cleaned up. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 1/12/2022

Inspection Photos



Photo 3. There is a hole at the outside edge compromising the secondary containment of the tank battery. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 1/12/2022

Inspection Photos



Photo 4. Facing north toward the tank battery. The area of disturbance south of the tank battery is bare of vegetation with compacted soils. This area needs to be reclaimed. Previous corrective action was not completed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 1/12/2022

Inspection Photos



Photo 5. Facing east approximately 275' west of the tank battery. A former spill had occurred in this area as shown by bare and oil stained soils. An electric fence has been installed around this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 1/12/2022

Inspection Photos



Photo 6. The soil at the spill area was dug a few inches down to show oily soils. The contaminated soils have not been cleaned up and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 1/12/2022

Inspection Photos



Photo 7. Facing toward the well site which is approximately 500' west of the tank battery.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06023 | Date: 1/12/2022