

Inspection Photos

API: 061-06780

Operator: MULL DRILLING COMPANY

Inspection Date: 1/11/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06780 | Date: 1/11/2022

Inspection Photos



Photo 1. Drone aerial photo facing west along the former access road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06780 | Date: 1/11/2022

Inspection Photos



Photo 2. Facing north toward the location. The area at the north side of the location has not established vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06780 | Date: 1/11/2022

Inspection Photos



Photo 3. Facing down toward the area that has not established vegetation which is approximately 100'x100' in size.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06780 | Date: 1/11/2022

Inspection Photos




Photo 4. Facing west toward the location. The area at the north side of the location has not established vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06780 | Date: 1/11/2022