

Inspection Photos

API: 061-06801

Operator: MULL DRILLING COMPANY

Inspection Date: 1/11/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06801 | Date: 1/11/2022

Inspection Photos



Photo 1. Center of the location facing north. There are mostly undesirable weeds throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06801 | Date: 1/11/2022

Inspection Photos



Photo 2. Center of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06801 | Date: 1/11/2022

Inspection Photos



Photo 3. Center of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06801 | Date: 1/11/2022

Inspection Photos



Photo 4. Center of the location facing east.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06801 | Date: 1/11/2022

Inspection Photos



Photo 5. Facing northwest at the location. There are areas with no desirable vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06801 | Date: 1/11/2022

Inspection Photos



Photo 6. Facing south toward the surrounding reference area which consists of desirable vegetation of Prairie sand reed, Blue grama, Sand drop seed, Sand sage among other native prairie species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06801 | Date: 1/11/2022