

Inspection Photos
Location Name: Piccolo A #1
API: 05-067-07186



Piccoli A #1 location overview.



95 bbl. produced water PBV near location entrance.

Inspection Photos
Location Name: Piccolo A #1
API: 05-067-07186



Piccoli A #1 location photo.



Earthen berm being constructed around double walled produced water PBV.

Inspection Photos
Location Name: Piccolo A #1
API: 05-067-07186



Well head is wet and stained.



Earthen berm being constructed at the time of this inspection.

Inspection Photos
Location Name: Piccolo A #1
API: 05-067-07186



Point source of Spill/Release #481402.



Earthen secondary containment berm around double walled steel PBV.

Inspection Photos
Location Name: Piccolo A #1
API: 05-067-07186



Recently installed perimeter berm. Wattles on SE corner of fill slope in response to Spill/Release Point ID #481402.



View from the SE corner of the location.

Inspection Photos
Location Name: Piccolo A #1
API: 05-067-07186



Wattles along fill slope.



Cottonwood Gulch contained flowing water at the time of this inspection.