

Inspection Photos

Location Name: LARAMIE ENERGY LLC OXY Federal /0797-08-51D Pad

Location ID: 324338



Photo #5691 from entrance to location.



Photo #5692 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC OXY Federal /0797-08-51D Pad

Location ID: 324338



Photo #5693 Storage tank not labeled.



Photo #5694 Sight glass indicates the storage tank is full of an unknown fluid.