

Inspection Photos

Location Name: LARAMIE ENERGY LLC OXY Federal /0708-11 Pad

Location ID: 324283



Photo #5697 from entrance to location.



Photo #5698 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC OXY Federal /0708-11 Pad

Location ID: 324283



Photo #5699 Storage tank not labeled.



Photo #5700 Sight glass indicates the storage tank is full of an unknown fluid.