

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT-66S95W /35SENW

Location ID: 335060



Photo #5703 from entrance to location.



Photo #5704 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PUCKETT-66S95W /35SENW

Location ID: 335060



Photo #5707 Vent pipe on tank open ended.