

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ARCO-TOSCO-66S95W /34SENE

Location ID: 335060



Photo #5713 from entrance to location.



Photo #5714 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC ARCO-TOSCO-66S95W /34SENE

Location ID: 335060



**Photo #5717 Vent pipe on tank open ended.**