



99999999

INSPECTION FORM

WELL NAME # Fehringer 1
OPERATOR Kestral Petro.
LOCATION NEWE 28-12N-52W
FIELD Pebble

API NUMBER 05 - -
PERMIT NUMBER _____
COUNTY Logan
INSPECTOR SP

AL/PA/DA INSPECTION RESULTS:

WELL STATUS:

PASS(Y) _____ FAIL(N) _____ DATE _____ FN _____ FD _____ WO _____

=====

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____
TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
SKIM PIT: _____ gal TANKS: () _____ bbls
EQUIPMENT _____
BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: _____ DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES _____ NO _____ PITS BACKFILLED: YES _____ NO _____
MATERIAL BURIED: YES _____ NO _____ NA _____ SITE CLEAN: YES _____ NO _____
BOND RELEASE OK: YES _____ NO _____ FED _____ HOLE MARKER: YES _____ NO _____

DATE OF SAFETY/STATUS INSPECTION _____

COMMENTS 8/9/89 Rods + Tbg pulled - on location.
TA. Well, battery + pit located
in SENE 28

05-075-07280



00823229