

**Inspection Photos**  
**Location Name: McCallum Unit 49**  
**Location ID: 324609**



**Photo 1. Access road not maintained for winter. Inspector unable to access location.**

