

Inspection Photos
Location Name: Sandau 24-34
Location ID: 328659



Production facility



Wellhead

Inspection Photos
Location Name: Sandau 24-34
Location ID: 328659



Wellhead



Temporarily abandoned wellhead

Inspection Photos
Location Name: Sandau 24-34
Location ID: 328659



Unused equipment and trash on 1/13/2022



Unused equipment and trash on 1/19/2022