

Inspection Photos
Location Name: Elton N Miller 2
Location ID: 318286



Pic 1 Wellhead, pump jack.



Pic 2 leaking gear box, stained soil needs to be cleaned up, oil on cement needs to be cleaned up.

Inspection Photos
Location Name: Elton N Miller 2
Location ID: 318286

Jan 18, 2022 at 1:38:53 PM
40.081880,-104.880031
Fort Lupton CO 80621
United States
COGCC



Pic 3 electric equipment.