

Inspection Photos
Operator: Simcoe
API: 067-07570
Date: 1/14/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing southward. Location largely snow covered, grasses observable through snow include slender wheatgrass and smooth brome.



Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised off irrigated grass field, largely snow covered at this time. Smooth brome is observable.