

Inspection Photos  
Operator: Simcoe  
API: 067-06601  
Date: 1/14/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing southward. Location largely snow covered, grasses observable through snow include sand dropseed and western wheatgrass.





Photo 3. View of musk thistles observed within the southern project area. Approximately 200 individuals from the previous growing season observed.



Photo 4. View of reference area comprised of irrigated grass field, largely snow covered at this time. Smooth brome is observable.