

Inspection Photos
Operator: Simcoe
API: 067-09307
Date: 1/14/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with rubber rabbitbrush, western wheatgrass, sand dropseed, and smooth brome.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of Russian knapweed plants from the previous growing season.



Photo 5. View of reference area comprised of pinyon and juniper woodland with sagebrush, squirreltail, penstemon, and pricklypear in the understory.