

Inspection Photos  
Operator: Simcoe  
API: 067-08969  
Date: 1/14/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Scattered wheatgrass plants observed. Operator needs to assess revegetation during the active growing season to ensure that revegetation is progressing according to 1003 reclamation rules.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area comprised of open grass field, largely snow covered at this time. Smooth brome is observable.