

Final Reclamation Inspection

January 11, 2022

Operator: NOBLE ENERGY INC - #100322

Location ID: 310232

Inspection Document #: 697503624

Weld County, CO

NENW Section 35 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources



Photo 1. Photo taken from the southern location, facing Northwest. Photo illustrates Operator has performed final reclamation activities. Snow cover inhibited Staff's ability to perform a thorough reclamation inspection; therefore, Staff will not make a final assessment for reclamation at this time. Undesirable vegetation appears to be managed. Unused equipment remains.

Inspection Photos

Location Name: 70 RANCHUSX BB #35-03

Location ID: 310232



Photo 2. Photo taken from the southern location, facing North. See comments under Photo 1.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Number: 697503624

Inspection Photos

Location Name: 70 RANCHUSX BB #35-03

Location ID: 310232



Photo 3. COGCC GISOnline aerial imagery with the flowline layer on illustrates that the remaining unused equipment (gas meter run and riser) is related to the PA well.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503624