

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-66S95W /27SESE

Location ID: 335403



Photo #5744 from entrance to location.



Photo #5745 Vent pipe on tank open ended.