

Inspection Photos

API: 071-06422

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/20/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06422 | Date: 1/20/2022

Inspection Photos



Photo 1. Facing east toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06422 | Date: 1/20/2022

Inspection Photos



Photo 2. There is a dripping water leak at the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06422 | Date: 1/20/2022

Inspection Photos



Photo 3. The shed door has not been reinstalled. Doors should be kept closed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06422 | Date: 1/20/2022

Inspection Photos



Photo 4. Well sign is labeled with API#.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06422 | Date: 1/20/2022