

Inspection Photos

API: 071-07335

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/20/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07335 | Date: 1/20/2022

Inspection Photos



Photo 1. Facing east toward the well site. The fence has been repaired around the pit and an extension pipe was added to the PW discharge.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07335 | Date: 1/20/2022

Inspection Photos



Photo 2. Facing southeast along the access road.



Inspection Photos



Photo 3. The ditch disturbance has been repaired and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07335 | Date: 1/20/2022