

Inspection Photos

API: 071-08723

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 1/20/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08723 | Date: 1/20/2022

Inspection Photos



Photo 1. Facing southeast along the access road. The culverts along the road have been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08723 | Date: 1/20/2022

Inspection Photos



Photo 2. The erosion gully has been repaired and armored with rock rip/rap.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08723 | Date: 1/20/2022

Inspection Photos



Photo 3. Facing southeast along the access road. The culverts along the road have been repaired. Areas of erosion have been repaired.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08723 | Date: 1/20/2022

Inspection Photos



Photo 4. Facing north toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08723 | Date: 1/20/2022