


## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY-66S95W /32SESE

Location ID: 334804



**Photo #5746 from entrance to location.**



**Photo #5747 from entrance to location.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY-66S95W /32SESE

Location ID: 334804



Photo #5748 from entrance to location.



Photo #5749 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY-66S95W /32SESE

Location ID: 334804



**Photo #5750 Vent pipe on tank open ended.**



**Photo #5751 Location lacks stabilization.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GRAND VALLEY-66S95W /32SESE

Location ID: 334804



**Photo #5753 Insufficient tracking BMP at entrance to location.**