

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSE

Location ID: 334700



Photo #5754 from entrance to location.



Photo #5755 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSE

Location ID: 334700



Photo #5757 Vent pipe on tank open ended.