

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC EXXON-66S95W /32SESE

Location ID: 323885



Photo #5758 from entrance to location.



Photo #5759 Vent pipe on tank open ended.