

Inspection Photos
Location Name: Grand #1
Location ID: 320118



Photo 1 Well head



Photo 2 Production equipment. Unused equipment communication tower laying on ground

Inspection Photos
Location Name: Grand #1
Location ID: 320118



Photo 3 TNK BTRY

Photo 4 Bird netting on produced water tank in disrepair.

Inspection Photos
Location Name: Grand #1
Location ID: 320118



Photo 5 Trash



Photo 6 loc pic

Inspection Photos
Location Name: Grand #1
Location ID: 320118



Photo 7 Road access.