

Inspection Photos
Location Name: Tom L Russell 2
Location ID: 318279



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Tom L Russell 2
Location ID: 318279



Photo 3 Pump Jack



Photo 4 ancillary equipment

Inspection Photos
Location Name: Tom L Russell 2
Location ID: 318279



Photo 5 Produced Water vault, flow line valves

Photo 6 Gas Meter Run Unused equipment

Inspection Photos
Location Name: Tom L Russell 2
Location ID: 318279



Photo 7 Horiz. Heated Sep.



Photo 8 Heater treater

Inspection Photos
Location Name: Tom L Russell 2
Location ID: 318279



Photo 9 TB sign.

Photo 10 TB

Inspection Photos
Location Name: Tom L Russell 2
Location ID: 318279



Photo 11 Flow line manifold.