

Inspection Photos

Location Name: Rawhide Flats 10-68-16

Location ID: 422460 API: 05-069-06436



Photo 1 Removed well flowline



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Rawhide Flats 10-68-16

Location ID: 422460 API: 05-069-06436



Photo 2 Well Excavation, cut & capped well



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Rawhide Flats 10-68-16

Location ID: 422460 API: 05-069-06436




Photo 3 Overview of Heater Treater and ECD area



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Rawhide Flats 10-68-16

Location ID: 422460 API: 05-069-06436



Photo 4 At approximate flowline riser location, looking east toward well



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Rawhide Flats 10-68-16

Location ID: 422460 API: 05-069-06436



Photo 5 Former Heater Treater location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Rawhide Flats 10-68-16

Location ID: 422460 API: 05-069-06436



COGCC

40.83956, -105.00303, 5522.7ft

01/24/2022 11:18:48

Photo 6 Former ECD location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Rawhide Flats 10-68-16

Location ID: 422460 API: 05-069-06436



Photo 7 Former Above Ground Storage Tanks location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources