

Inspection Photos

API: 071-09185

Operator: OGRIS OPERATING LLC

Inspection Date: 1/24/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09185 | Date: 1/24/2022

Inspection Photos



Photo 1. Facing northwest toward the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09185 | Date: 1/24/2022

Inspection Photos



Photo 2. Facing south toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09185 | Date: 1/24/2022

Inspection Photos



Photo 3. Facing north toward the fill slope. The vegetation is well established in this area of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09185 | Date: 1/24/2022