

Inspection Photos

API: 071-06219

Operator: OGRIS OPERATING LLC

Inspection Date: 1/24/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06219 | Date: 1/24/2022

Inspection Photos



Photo 1. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06219 | Date: 1/24/2022

Inspection Photos



Photo 2. Facing west toward the TA well. The vegetation is well established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06219 | Date: 1/24/2022