

Inspection Photos

API: 071-09582

Operator: OGRIS OPERATING LLC

Inspection Date: 1/24/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09582 | Date: 1/24/2022

Inspection Photos



Photo 1. Facing northeast toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09582 | Date: 1/24/2022

Inspection Photos



Photo 2. Facing east toward the cut slope. The vegetation is well established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09582 | Date: 1/24/2022

Inspection Photos



Photo 3. Facing northeast toward the wellsite.

