

Final Reclamation Inspection

January 24, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 306532

Inspection Document #: 697503652

Weld County, CO

SWNW Section 2 T6N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: ANDERSON #12-2
Location ID: 306532



Photo 1. Photo taken from the well location, facing South. Photo illustrates the well location is within an agricultural storage area (manure pile).

Inspection Photos
Location Name: ANDERSON #12-2
Location ID: 306532



Photo 2. Photo taken from the well location, facing West. See comments under Photo 1.



Inspection Photos
Location Name: ANDERSON #12-2
Location ID: 306532




Photo 3. Google Earth aerial imagery from 6/19/2014 illustrates the well location was within an agricultural production field.

Inspection Photos
Location Name: ANDERSON #12-2
Location ID: 306532




Photo 4. Google Earth aerial imagery from 9/7/2016 now illustrates the well location within an agricultural storage area and has been such ever since.

Inspection Photos
Location Name: ANDERSON #12-2
Location ID: 306532



Photo 5. COGCC GISOnline aerial imagery illustrates no remediation issues at the well location but the associated offsite tank battery has an open remediation which is tied to the adjacent well to the east (123-24860).