

Inspection Photos  
Operator: Simcoe  
API: 067-07777  
Date: 1/24/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the northern fill slope from the northeastern corner facing westward. Revegetation is progressing with intermediate wheatgrass, crested wheatgrass, western wheatgrass, and rubber rabbitbrush.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of pinyon juniper woodland with understory of sagebrush, antelope bitterbrush, prickly pear, James galleta, and mat penstemon.