

Inspection Photos
Location Name: Knight Pad
Location ID: 457362



Photo #1 Location & Start of odor measurement “not detected”

Photo #2 Location & End of odor measurement “not detected”

Inspection Photos
Location Name: Knight Pad
Location ID: 457362



Photo #3 Adequate grounding

Photo #4 Adequate grounding

Inspection Photos
Location Name: Knight Pad
Location ID: 457362



**Photo #5 Not Adequate grounding on north Frack tanks/
Equipment**

**Photo #6 Not Adequate grounding on north Frack tanks/
Equipment**

Inspection Photos
Location Name: Knight Pad
Location ID: 457362



Photo #7 Stained Soil

Photo #8 Stained Soil

Inspection Photos
Location Name: Knight Pad
Location ID: 457362



Photo #9 Not on secondary containment

Photo #10 Not on secondary containment