

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NESW

Location ID: 324018



**Photo #5772 from entrance to location.**




**Photo #5774 Vent pipe on tank open ended.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NESW

Location ID: 324018



**Photo #5775 Access road lacks stabilization.**



**Photo #5776 Access road lacks stabilization.**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNOCAL-67S96W /1NESW

Location ID: 324018



**Photo #5777 Insufficient tracking BMP at entrance to location.**