

Final Reclamation Inspection

December 14th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 331079

Inspection Document #: 701900289

SESW Section 22 T3N R68W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Weingardt 24-22
Location ID: 331079



Photo 1. 2020 aerial imagery of the well pad and tank battery (north is up).
Note: Another tank battery remains to service wells on site that are owned by another operator.

Inspection Photos
Location Name: Weingardt 24-22
Location ID: 336478



Photo 2. Overview photo of the well pad taken at ground level from north of the well looking south. Note: Well pad (indicated by red arrow) falls in a horse corral/pasture and is about 150 yards from where photo was taken. No signs of oil and gas equipment observed.

Inspection Photos
Location Name: Weingardt 24-22
Location ID: 336478



Photo 3. Overview photo of the tank battery taken at ground level from the western edge looking east. Note: photo shows that minimal reclamation activities have been attempted.